

Follow this process to install your 85563A/64A 3-in-1 calibration kit.

1. Unpack & Inspect



2. Verify Shipment Using Box Contents List





Remove the Certificate of Calibration & 4. Attach 85563A/4A to instrument save for reference







